

MATERIALS		
BODY	BRASS NICKEL PLATED	
CONTACT	GOLD PLATED	
INSULATOR	PTFE	
3		




## ASSEMBLY PROCEDURES

1. SLIDE CLAMP NUT (1), WASHER (2) & GASKET (3) OVER CABLE. STRIP CABLE AS SHOWN. DO NOT NICK BRAID WHILE CUTTING JACKET. TAPER END OF BRAID TO PERMIT ASSEMBLY OF BRAID CLAMP (4). SLIDE BRAID CLAMP (4) OVER BRAID & SEAT AGAINST CABLE.



.600

2. FORM BRAID OVER CLAMP NUT (4). TRIM BRAID BACK TO SHOULDER. CUT DIELECTRIC & CENTER CONDUCTOR TO DIMENSION SHOWN. DO NOT NICK CENTER CONDUCTOR. SOLDER CONTACT TO CENTER CONDUCTOR. REMOVE EXCESS SOLDER. DO NOT OVER HEAT DIELECTRIC. INSERT CABLE ASSEMBLY INTO BODY & TIGHTEN.



NOTE: INSERT PTFE BEFORE CONTACT. WITH LARGE OPEN END SLIDING OVER CENTER CONDUCTOR & DIELECTRIC.

CENTER II	.DING 1, YONGFU SCIE Ndustrial Park, Nai 3900,dongguan, gu	NZHA DISTRICT	ſ <b>5</b> ,	3Y	
ESTABLISHED 1972					
dwg ntle <b>E</b> T <b>10</b> 722	DES. MHV FEMALE, CLAMP ATTACHMENT FOR RG174, RG188 & RG316				
SIZE A FSCM NO. 53919	CAD FILE 062502	SCALE N/A		127	
NOTES: 1. UNLESS OTHERWISE SPECIFIED A 2. ALL SPECIFICATIONS ARE SUBJECT				F	