


STRIPPING DIMENSIONS

ASSEMBLY PROCEDURES

- 1. STRIP CABLE AS SHOWN.
- 2. PUSH BRAID BACK AGAINST CABLE JACKET EVENLY.
- 3. INSERT CABLE INTO BODY WHILE TWISTING CONNECTOR SLIGHTLY.
- 4. INSERT ASSEMBLY INTO COMPRESSION TOOL & COMPRESS USING A PE5012.





8TH FLOOR, BUILDING 1, YONGFU SCIENCE AND TECHNOLOGY CENTER INDUSTRIAL PARK, NANZHA DISTRICT 5, HUMEN,523900, DONG GUAN, GUANGDONG, CHINA

> WEBSITE: www.ebeestock.com EMAIL: sales@ebeestock.com

DWG	TITLE

ET10557

NOTES:
1. UNLESS OTHERWISE SPECIFIED ALL DIMENSIONS ARE NOMINAL.
2. ALL SPECIFICATIONS ARE SUBJECT TO CHANGE WITHOUT NOTICE AT ANY TIME.
3. DIMENSIONS ARE IN INCHES [mm].
4. FITS MIL-C-17 AND EQUIVALENT CABLES.

FSCM NO. 53919

CAD FILE 011409-B

SCALE N/A

SIZE A

XXXX