

MHV Male Connector Clamp/Solder Attachment for RG58, RG55,


ASSEMBLY PROCEDURES RG141, RG142, RG223, RG400, RG303, PE-C195, PE-P195, LMR-1952 RFF


1. SLIDE CLAMP NUT (1), WASHER (2) & GASKET (3) OVER CABLE AS SHOWN.




2. TRIM PER DIMENSIONS.







4. INSTALL CONTACT BY SOLDERING TO CABLE CENTER CONDUCTOR LEAVING NO GAPS (5).



5. REMOVE EXCESS SOLDER. INSERT ASSEMBLY INTO CONNECTOR BODY AND TIGHTEN NUT.

,	, ,	[38.6]	-
		1.382 ± 0.012 [35.1 ± 0.3]	
0.57 ø [14.5]	PAS		
00	LABEL "PASTERNACK"	7/16 FLATS	7/16 HEX

STANDARD TOLERANCES

±0.2 .X XX. ±0.1 XXX. ± 0.05

*STANDARD TOLERANCES APPLY ONLY TO DIMENSIONS IN INCHES



ebeestock

8TH FLOOR, BUILDING 1, YONGFU SCIENCE AND TECHNOLOGY CENTER INDUSTRIAL PARK, NANZHA DISTRICT 5, HUMEN,523900, DONG GUAN, GUANGDONG, CHINA

> WEBSITE: www.ebeestock.com EMAIL: sales@ebeestock.com

DWG	IIILE
	ET10704

NOTES:

1. UNLESS OTHERWISE SPECIFIED ALL DIMENSIONS ARE NOMINAL.

2. ALL SPECIFICATIONS ARE SUBJECT TO CHANGE WITHOUT NOTICE AT ANY TIME.

3. DIMENSIONS ARE IN INCHES [mm].

050216

FSCM NO. 53919

CAD FILE

SCALE N/A

SIZE A

3045